

Q-269R1



SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.fleet.ford.com/truckbbas (click "Contact Us")

Toll-free: (877) 840-4338

QVM Bulletin: Q-269R1

Date: 02 March, 2017

Revised: 19 May, 2017

Erratic Operation of Electrical Features with Snow Plow and Other High Electrical Load Devices

Revision	Update	Revision Date
Q-269R1	• Updated to reflect current TSB information	19 May, 2017

Models Affected: 2017 F-Super Duty – All Models with 6.2L & 6.8L Gasoline Engine and built on or before 08 April, 2017

Issue: Some 2017 F-Super Duty vehicles equipped with a 6.2L or 6.8L gasoline engine and built on or before 08-Apr-2017 may exhibit any or all of the following concerns at times of high electrical system draw such as snow plow operation, instrument cluster backlighting inoperative, erratic climate control blower motor operation, the red brake warning indicator flickering, and/or low battery - features temp turned off message in the message center.

Solution: Technical Service Bulletin #TSB 17-0043 has been issued to perform required service at a Ford Motor Company Dealership. Follow the Service Procedure steps contained in the TSB to correct the condition.

Please contact your servicing Ford Dealer for more information on this TSB and service procedure.

If you have any questions concerning the content of this Bulletin, please contact the Ford Truck Body Builders Advisory Service as shown in the header.